

Hewlett Packard - www.hp.de

Model	Latest Firmware	Compatibility to		
		4x	6x	BD-RE 2x
BD340i	XH21	4x	6x	2x

Hewlett Packard Support Service : <http://www8.hp.com/de/de/support-drivers.html>

LG - www.lg.com/de

Model	Latest Firmware	Compatibility to		
		4x	6x	BD-RE 2x
BH12NS30	EL00	4x	6x	2x
BH10NS30	EL00	4x	6x	2x
BH08NS20	1.00	4x	6x	2x
GGW-H20N	XL05	4x	4x	2x
GBW-H10N	GL06	4x	-	2x
BPO6LU10	HL03	4x	6x	2x
BT20N	KN02	4x	6x	2x
BT10N	GJ01	4x	6x	2x

LG Support Service : <http://www.lg.com/de/support/product/support-product.jsp>

LITEON - www.liteonit.eu/de/

Model	Latest Firmware	Compatibility to		
		4x	6x	BD-RE 2x
BD-4B1S	7P5B	4x	4x	2x
BDD 1001	BDIN	2x	2x	2x

Liteon Support Service : <http://www.liteonit.eu/de/firmware-und-anderes.html>

Panasonic - www.panasonic.de

Model	Latest Firmware	Compatibility to		
		4x	6x	BD-RE 2x
SW-5584	1.00	4x	6x	2x
LF-PB371	1.03	4x	6x	2x
LF-PB271	1.03	4x	4x	2x
SW-5582	BGF2	2x	2x	2x
LF-MB121	BD04	2x	2x	2x
UJ-240AS	1.00	4x	4x	2x
UJ-235	1008	4x	4x	2x
UJ-220	1003	2x	2x	2x
UJ-210	1.20	1x	1x	1x

Panasonic Support Service : http://www.panasonic.de/html/de_DE/Support/17471/index.html

Philips - www.philips.de

Model	Latest Firmware	Compatibility to		
		4x	6x	BD-RE 2x
SPD7000P	BPBM	2x	2x	2x

Philips Support Service : http://www.support.philips.com/support/sms_page.jsp?userLanguage=de&userCountry=de

Pioneer - www.pioneer.de

Model	Latest Firmware	Compatibility to		
		4x	6x	BD-RE 2x
BDR-206	1.06	4x	6x	2x
BDR-205	1.12	4x	6x	2x
BDR-203B	1.11	4x	6x	2x
BDR-202B	1.08	4x	-	2x
BDR-TD01	1.05	4x	-	2x

Panasonic Support Service : http://www.panasonic.de/html/de_DE/Support/17471/index.html

Plextor - www.plextor-digital.com

Model	Latest Firmware	Compatibility to		
		4x	6x	BD-RE 2x
PX-B940SA	1.08	4x	6x	2x
PX-B920SA	1.03	4x	4x	2x
PX-B910SA	1.01	4x	4x	2x

Plextor Support Service : <http://www.plextor-digital.com/index.php/de/Support/>

QSI -

Model	Latest Firmware	Compatibility to		
		4x	6x	BD-RE 2x
SPD7000P	BPBM	2x	2x	2x

QSI Support Service : <http://www>

SONY OPTIARC - www.sony-optiarc.eu

Model	Latest Firmware	Compatibility to		
		4x	6x	BD-RE 2x
BWU-500S	1.63	4x	6x	2x
BWU-300S	1.0c	4x	6x	2x
BWU-200S	1.0b	4x	4x	2x
BWU-100A	1.0f	2x	2x	2x
BD RW BD-5730S	1.02	4x	4x	2x

Sony Optiarc Support Service : <http://www.sony-optiarc.eu/supportservice/downloads.html>

Please make sure, that your burner is always running by the latest firmware. Only if this requirement is given, we can guarantee you, to use our medias without any problems. You can download the updates for free on the website of the manufacturer.

Bitte achten Sie darauf, dass Ihr Brenner stets unter der neuesten Firmware läuft. Nur dann können wir Ihnen versichern, dass unsere Medien problemlos mit Ihrem Gerät verwendet werden können. Die entsprechenden Firmwareupdates können Sie der Website des Herstellers entnehmen und stehen kostenlos zur Verfügung.

Latest Update: March 2012